



Produced by the United States Geological Survey
in cooperation with California
Department of Water Resources
Control by USGS and NOS/NOAA
Compiled from aerial photographs taken 1974. Topography by
plane-table surveys 1976. Map edited 1978
Selected hydrographic data compiled from NOS/NOAA charts
18661 and 18662 (1976). This information is not intended for
navigational purposes
North American Datum of 1927 (NAD 27). Projection and
10 000-foot grid ticks: California Coordinate System,
zone 2 (Lambert Conformal Conic)
1000-meter Universal Transverse Mercator grid ticks, zone 10
shown in blue
The difference between NAD 27 and North American Datum of
1983 (NAD 83) for 7.5 minute intersections is given in USGS
Bulletin 1875. The NAD 83 is shown by dashed corner ticks
Red tint indicates areas in which only landmark buildings are shown

UTM GRID AND 1983 MAGNETIC NORTH
DECLINATION AT CENTER OF SHEET
15° 15' 14 MILS
276 MILS
Fine red dashed lines indicate selected fence and field lines where
generally visible on aerial photographs. This information is unchecked
This map lies within a subsidence area
Vertical control based on latest available adjustment
Yolo Bypass area subject to inundation during periods of high water

CONTOUR INTERVAL 10 FEET
DOTTED LINES REPRESENT 5-FOOT CONTOURS
NATIONAL GEODETIC VERTICAL DATUM OF 1929
DEPTH CURVES AND SOUNDINGS IN FEET—DATUM IS MEAN LOWER LOW WATER
SHORELINE SHOWN REPRESENTS THE APPROXIMATE LINE OF MEAN HIGH WATER
THE RELATIONSHIP BETWEEN THE TWO DATUMS IS VARIABLE
THE MEAN RANGE OF TIDE IS APPROXIMATELY 2 FEET
SCALE 1:24 000
1 000 2 000 3 000 4 000 5 000 6 000 7 000 FEET
1 5 0 1 KILOMETER
THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS
FOR SALE BY U.S. GEOLOGICAL SURVEY
DENVER, COLORADO 80225, OR RESTON, VIRGINIA 22092
A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

ROAD CLASSIFICATION
Primary highway, hard surface
Secondary highway, hard surface
Light-duty road, hard or improved surface
Unimproved road
Interstate Route
U. S. Route
State Route
QUADRANGLE LOCATION
CALIF.
RIO VISTA, CALIF.
38121-B6-TF-024
1978
MINOR REVISION 1993
DMA 1660 II NW-SERIES V895
Photosinspected from 1991 source; no major culture or
drainage changes observed. Boundaries, other than
corporate, and names verified 1993